

DAMAGE REPORT

Inbound carrier: MAERSK NAKURU
 MNKR347S 347S 25-Nov-2023 05:24

Container	Damage type	Damage location
CAAU5760833	DENT	LEFT
MAEU4061059	CUT	TARPAULIN
MRSU5084166	IMO LABEL	RIGHT
MRSU5084166	IMO LABEL	FRONT
HASU4080192	DENT	LEFT
SUDU7782657	DENT	DOORSYSTEM
CAAU5756514	DENT	RIGHT
TCKU6430648	BULGED	LEFT
MSKU6779716	DENT	LEFT
MRKU0058433	BULGED	RIGHT

MAERSK NAKURU
FOR RECEIPT ONLY

Without any liability accepted
 Constanta South Container Terminal
 Planning Department