

DAMAGE REPORT

Inbound carrier: CAPE MALE

CMAL424N 424N

11-Jun-2024 02:39

Container	Damage type	Damage location
MSKU9098716	DENT	RIGHT
MSKU9098716	BENT	LEFT
BEAU5899004	BENT	RIGHT
BEAU5899004	BENT	LEFT
TTNU1260422	BENT	RIGHT
AMFU2983946	CUT	TARPAULIN
MRKU7261421	BENT	BOTTOM
MRKU9610060	DENT	LEFT
SUDU7525073	BENT	BOTTOM
MRKU5995663	DENT	CORNERPOST
TLLU1554662	CUT	TARPAULIN
MNBU9093203	DENT	CORNERPOST
SJKU2414189	CUT	TARPAULIN
MRSU5856758	BENT	LEFT
MRSU5856758	BENT	RIGHT
MAEU3442282	CUT	TARPAULIN
MWCU5300840	DENT	RIGHT
MWCU5300840	DENT	CORNERPOST
MWCU5300840	DENT	TOPROOF
MWCU5300840	DENT	LEFT
TRHU5018850	IMO LABEL	DOOR
MRKU4267112	DENT	LEFT
HASU4933021	DENT	LEFT
MRKU5771160	IMO LABEL	FRONT
MRKU5771160	IMO LABEL	DOOR
MRKU3195189	DENT	RIGHT
MRSU5918314	DENT	RIGHT
TGHU1658708	BENT	BOTTOM

MV CAPE MALE
P.O.R. Majuro
IMO 701750
Call Sign 7RU3
GRT 2572 NET 19672

*AS RECEIPT ONLY
DISCHARGED &
LOADED*

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRKU7789342	BENT	BOTTOM
MRKU7789342	BENT	LEFT
FCIU4259941	DENT	RIGHT
TRHU4397256	BENT	RIGHT
HASU4453568	DENT	LEFT
MSKU1103652	DENT	LEFT
TGHU9886725	DENT	DOORSYSTEM
MRKU7319945	DENT	RIGHT
PONU7692550	DENT	RIGHT
PONU7692550	DENT	CORNERPOST
MMAU1135962	DENT	TOPROOF
MMAU1135962	BENT	LEFT
MMAU1135962	DENT	CORNERPOST
MSKU0020044	BENT	RIGHT
MSKU0020044	DENT	LEFT
SUDU6156793	BENT	RIGHT
SUDU6156793	BENT	LEFT
MAEU9250029	BENT	CORNER
GCXU5797754	DENT	RIGHT
MAEU4108388	CUT	TARPAULIN
MRKU6671226	BENT	BOTTOM
MRKU6671226	DENT	CORNERPOST
MRKU6671226	DENT	LEFT
MRKU6670873	BENT	BOTTOM
MNBU3083023	BENT	LEFT
MNBU3932012	DENT	CORNERPOST
CAXU5789174	CUT	TARPAULIN
MSKU1977935	DENT	RIGHT
MRKU3859499	DENT	FRONT
MRKU3859499	DENT	RIGHT
TRHU4758868	DENT	LEFT
MSKU5994036	DENT	RIGHT
PONU8065575	DENT	LEFT
PONU8065575	DENT	RIGHT

MV CAPE MALE
P.O.R. Majuro
IMO 9440150
Call Sign V7RU3
GRT 53875 NRT 19672

AS RECEIPT ONLY
DISCHARGED &
LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
UESU4664449	BENT	RIGHT
UESU4664449	DENT	RIGHT
UESU4664449	DENT	LEFT
HASU1426677	BENT	LEFT
TCKU1629025	LOOSE	CORNER
TCKU1629025	RIPPED	CORNER
TCKU1629025	TORN	CORNER
TCKU1629025	BROKEN	CORNER
UETU5694884	DENT	LEFT
CAIU4992009	HOLE	TOPROOF
MRKU3094028	DENT	RIGHT
SPLU0700481	CUT	TARPAULIN
MRKU2682829	DENT	RIGHT
MRKU2682829	DENT	CORNERPOST
HASU4075827	DENT	RIGHT
HASU4075827	DENT	LEFT
HASU4847710	DENT	CORNERPOST
MNBU0106819	DENT	RIGHT
MNBU0106819	DENT	LEFT
MNBU3084375	DENT	RIGHT
MNBU3084375	DENT	LEFT
MRKU5301968	DENT	RIGHT
MRKU5301968	DENT	CORNERPOST
MNBU3962716	DENT	RIGHT
MNBU3962716	DENT	LEFT
PONU1738334	DENT	RIGHT
PONU1738334	DENT	LEFT
SUDU6778101	DENT	FRONT
SUDU6778101	DENT	RIGHT
SUDU6778101	BENT	RIGHT
MRKU5499750	DENT	LEFT
MRKU7833065	DENT	CORNERPOST
MRKU6847866	DENT	RIGHT
MRKU6847866	BENT	LEFT

MV CAPE MALE
P.O.R. M. Juro
IMO 440150
Call Sign V7R03
GRT 75375 NRT 19672

AS RECEIPT ONLY,
DISCHARGED AS
LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
SJKU2417790	CUT	TARPAULIN
UESU3000430	CUT	TARPAULIN
UESU3000430	DENT	DOORSYSTEM
SEGU7318348	CUT	TARPAULIN
SJKU2414928	DENT	RIGHT
SJKU2414928	CUT	TARPAULIN
SUDU2843831	CUT	TOPROOF
SJKU2417763	CUT	TARPAULIN
MRKU5935160	BENT	RIGHT
MSKU9380740	BENT	RIGHT
MSKU9380740	BENT	LEFT
MRKU6794663	DENT	RIGHT
MRSU4015978	DENT	CORNERPOST
MRKU2049019	DENT	LEFT
MRKU5961597	BENT	BOTTOM
MRKU5943187	BENT	RIGHT
MRKU5943187	DENT	LEFT
MRKU5943187	DENT	CORNERPOST
MSKU9399134	RUSTED	FRONT
MSKU9399134	RUSTED	BACK
MSKU9399134	DENT	LEFT
CAAU5270409	BENT	RIGHT
CAAU5270409	BENT	LEFT
MRKU6235979	IMO LABEL	RIGHT
MRKU6804186	DENT	RIGHT
MRKU6804186	DENT	LEFT
MRKU7074760	DENT	RIGHT
MRKU7074760	DENT	LEFT
MSKU4313523	BENT	LEFT
TGBU9345713	DENT	LEFT
MSKU0106997	BROKEN	DOORSYSTEM
GLDU5584649	BENT	RIGHT
GLDU5584649	DENT	RIGHT
GLDU5584649	BENT	LEFT

MV CAPE MALE
P.O.R. Majuro
IMO 490150
Call Sign VTRUB
GRT 35078 NRT 19672

AS RECEIPT ONLY
DISCHARGED AS
LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
TRHU2108930	BENT	BOTTOM
TRHU2108930	BENT	RIGHT
MAEU4123510	CUT	TARPAULIN
MAEU4123510	HOLE	TARPAULIN
MSKU7529959	BENT	BOTTOM
MSKU7529959	RUSTED	RIGHT
MSKU7529959	DENT	LEFT
XINU1346468	DENT	DOORSYSTEM
XINU1346468	DENT	LEFT
SUDU1969194	BENT	RIGHT
MSKU0337297	DENT	LEFT
MSKU0337297	BENT	RIGHT
MRKU4117621	BENT	RIGHT
MRSU3705984	DENT	RIGHT
MRSU3705984	BENT	LEFT
MMAU1292299	DENT	LEFT
MSKU3082395	DENT	LEFT
MSKU3260440	DENT	RIGHT
MSKU9384746	DENT	RIGHT
MSKU9384746	DENT	LEFT
TGHU0895665	DENT	LEFT
SUDU7352506	BENT	FRONT
SJKU2414527	CUT	TARPAULIN
MRKU3482682	DENT	RIGHT
SUDU6515466	BENT	RIGHT
SUDU6515466	DENT	LEFT
SEKU4710257	BENT	RIGHT
SEKU4710257	DENT	RIGHT
SEKU4710257	DENT	CORNERPOST
MSKU0267266	BENT	RIGHT
MSKU8904838	HOLE	TOPROOF
MIEU3017145	IMO LABEL	FRONT
MIEU3017145	IMO LABEL	DOOR
HASU5067528	DENT	LEFT

MV CAPE MALE
 P.O.R. Major6
 IMO 9440150
 Call Sign VTRU3
 GRT 33978 NRT 19672

AS RECEIPT ONLY
 DISCHARGED AS
 LOADED

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
CAXU8095161	DENT	CORNERPOST
CAXU8095161	DENT	LEFT
MSKU0839090	IMO LABEL	DOOR
CNIU2450984	IMO LABEL	FRONT
CNIU2450984	IMO LABEL	RIGHT
CNIU2450984	IMO LABEL	DOOR
CNIU2450984	IMO LABEL	LEFT
MRSU3847865	BENT	RIGHT
MRSU3847865	DENT	CORNERPOST
MRSU3847865	BENT	LEFT
MRSU3847865	DENT	LEFT
MRKU4633736	BENT	RIGHT
MMAU1011112	BENT	RIGHT
MMAU1011112	DENT	TOPROOF
MMAU1011112	BENT	LEFT
MMAU1011112	CUT	FRONT
SUDU6658750	BENT	RIGHT
MRKU5101912	IMO LABEL	FRONT
MSKU0292567	BENT	LEFT
SUDU6789554	DENT	LEFT
MRKU1109371	DENT	CORNERPOST
MSKU1097570	DENT	RIGHT
MSKU1097570	DENT	LEFT
GESU3696263	BENT	BOTTOM
MRKU8969288	DENT	RIGHT
MRKU2465654	DENT	LEFT
MNBU0095416	BENT	RIGHT
MNBU0095416	BENT	LEFT
TRHU6318641	BENT	LEFT
SUDU8171288	DENT	RIGHT
SUDU8171288	DENT	LEFT
MSKU0324854	DENT	CORNERPOST
MSKU0324854	BENT	LEFT
MSKU1707729	BENT	LEFT

MV CARE MALE
P.O.B. Aajuro
IMC 440150
Call Sign V7RU3
GRT 3378 NRT 19672

AS RECEIPT ONLY,
DISCHARGED AS
LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRKU3573102	BENT	RIGHT
MRKU9155922	BENT	BOTTOM
MRKU9155922	BENT	LEFT
MRKU9155922	DENT	CORNERPOST
MRKU7622273	DENT	LEFT
MSKU5253840	BENT	BOTTOM
MSKU5253840	DENT	CORNERPOST
SUDU1306062	BENT	BOTTOM
SUDU1306062	DENT	LEFT
MRKU5351423	DENT	LEFT
MRSU4301544	BENT	LEFT
MRSU4049896	DENT	LEFT
MRKU8729245	DENT	RIGHT
MRKU8729245	BENT	LEFT
MRKU7445671	DENT	CORNERPOST
MSKU7364843	BENT	BOTTOM
MSKU7364843	BENT	RIGHT
MRKU8746303	DENT	RIGHT
TRHU8424405	BENT	LEFT
MSKU0729662	HOLE	TOPROOF
SJKU2415863	CUT	TARPAULIN
CAAU6556932	BENT	RIGHT
MRKU6180937	DENT	LEFT
TCKU7008684	BENT	RIGHT
SUDU7641767	BENT	BOTTOM
SUDU7641767	DENT	LEFT
CAXU9174624	DENT	LEFT
MNBU0517975	DENT	LEFT
MNBU0517975	DENT	CORNERPOST
PONU7488660	DENT	RIGHT
PONU7488660	DENT	CORNERPOST
PONU7488660	DENT	LEFT
MMAU1384142	DENT	CORNERPOST
MRKU3581520	BENT	RIGHT

MV CAPE MALE
P.O.R. Majuro
IMO 440150
Call Sign V7RU3
GRT 35378 NRT 19672

SIGNED AS
RECEIPT ONLY
DISCHARGED AS
LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
GCXU1008420	CUT	TARPAULIN
MWCU6987113	DENT	RIGHT
MWCU6987113	DENT	TOPROOF
MWCU6987113	BENT	LEFT
MSKU8711090	BENT	FRONT
MSKU0582329	BENT	RIGHT
MSKU0582329	DENT	CORNERPOST
XINU8183280	BENT	RIGHT
MSKU9038297	BENT	RIGHT
MSKU9038297	DENT	LEFT
MNBU0577953	BENT	RIGHT
MRSU4055203	DENT	RIGHT
MSKU1417210	DENT	LEFT
MRKU7096501	DENT	LEFT
MSKU4443810	DENT	RIGHT
SUDU1353207	BENT	BOTTOM

MV CAPE MALE
P.O.R. Majaro
IMO 4470150
Call Sign W7RU3
GRT 35878 NRT 19672

SIGNED AS
RECEIPT ONLY
DISCHARGED
AS LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department