

**DAMAGE REPORT**

Inbound carrier: CAPE MALE  
CMAL501S 501S 09-Jan-2025 16:09

Container	Damage type	Damage location
MAEU4647543	CUT	TOPROOF
MRKU8217589	BENT	RIGHT
MRSU3997736	BENT	RIGHT
MRSU0555427	DENT	RIGHT
MSKU7892943	DENT	CORNERPOST
MRKU5181076	DENT	LEFT
MSKU1577292	DENT	LEFT
TRHU5097377	BENT	LEFT
MRKU4908540	DENT	LEFT
MSKU6708287	HOLE	FRONT
SUDU6819324	DENT	RIGHT
MRSU5923814	BENT	LEFT
MRSU5923814	BENT	RIGHT
MAEU4177558	CUT	TARPAULIN
CAAU5407852	DENT	RIGHT
TCKU6921343	BENT	FRONT
HASU4490108	DENT	RIGHT
TRHU1148922	BENT	RIGHT
GCXU5766959	BENT	RIGHT
GCXU5766959	BENT	LEFT
TRHU5673636	DENT	RIGHT
MSKU7011208	DENT	LEFT
MSKU1975022	BENT	RIGHT
CAIU4925905	BENT	LEFT
HASU4211836	DENT	RIGHT
HASU4211836	DENT	LEFT
CIPU5204874	DENT	RIGHT
TLLU2207061	BENT	RIGHT

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

MV "CAPE MALE"  
 CALL SIGN: V7RU3  
 OFF-No.: 3580  
 GRT: 35878  
 POWER: 25040 KW

SIGNED AS RECEIPT ONLY AND NOT ACCEPTANCE OF RESPONSIBILITY, CARGO DISCHARGED AS LOADED.

Container	Damage type	Damage location
TCKU6574711	DENT	RIGHT
MRKU3775166	BENT	LEFT
MRKU2049148	DENT	LEFT
MRKU2049148	DENT	RIGHT
MRSU3597220	BENT	RIGHT
TRLU6929422	BENT	LEFT
MRKU4409027	DENT	FLOOR
MRKU9300044	DENT	CORNER
GCXU5817552	BENT	RIGHT
MNBU0157673	HOLE	RIGHT
MRKU7516250	BENT	LEFT
MRKU0372212	DENT	LEFT
MRSU6341417	BENT	LEFT
MSKU0883220	BENT	RIGHT
MSKU0883220	BENT	LEFT
MSKU1163409	CUT	RIGHT
MRSU4818199	DENT	LEFT
MWCU5313657	DENT	LEFT
SEKU4487272	DENT	RIGHT
SUDU6881260	DENT	LEFT
HASU4175298	BENT	LEFT
MSKU0715231	BENT	FRONT
MNBU0026668	DENT	RIGHT
MSWU1042326	DENT	LEFT
TLLU5270638	DENT	LEFT
MSKU2510502	BENT	LEFT
BMOU4179998	DENT	RIGHT
HASU1012002	BENT	LEFT
TCLU8245728	BENT	LEFT
MNBU3954813	CUT	DOOR
MRKU2663921	BENT	RIGHT
MRKU2663921	DENT	LEFT
MRSU6494479	DENT	RIGHT
MRKU8430172	DENT	RIGHT

Without any liability accepted  
 Consists South Container Terminal  
 Planning Department

MV "CAPE MALE"  
 CALL SIGN: V7RU3  
 OFF-No.: 3580  
 GRT: 35578  
 POWER: 25040 KW

SIGNED AS RECEIPT ONLY AND NOT ACCEPTANCE  
 OF RESPONSIBILITY, CARGO DISCHARGED AS LOADED

Container	Damage type	Damage location
MRKU8430172	DENT	LEFT
TCKU6795630	DENT	LEFT
MRSU3185429	DENT	RIGHT
HASU5160353	BENT	LEFT
GESU6565483	BENT	LEFT
FFAU5618859	HOLE	TOPROOF
MMAU1049648	DENT	RIGHT
TGBU9665980	DENT	LEFT
MSKU8667016	DENT	LEFT
MRKU4178843	DENT	LEFT
MRKU5939314	DENT	LEFT
MRSU0081523	BENT	CORNER
CAAU5312968	DENT	RIGHT
HASU4217515	DENT	RIGHT
MRSU3426362	BENT	LEFT
MRKU3086423	DENT	RIGHT
MNBU0056071	BENT	LEFT
MRKU2537538	DENT	RIGHT
MRKU7271780	BENT	RIGHT
MRSU0030043	BENT	LEFT
MRKU8002960	DENT	FRONT
TCKU7017161	BENT	RIGHT
SUDU4877065	DENT	RIGHT
MMAU1246396	DENT	RIGHT
CAAU6367414	DENT	LEFT
MRSU4179610	DENT	LEFT
MMAU1158000	DENT	RIGHT
TLLU5882973	DENT	RIGHT
SUDU6124585	DENT	LEFT
MRKU6952033	BENT	LEFT
MRKU6131737	DENT	RIGHT
HASU4950482	BENT	RIGHT
HASU4950482	BENT	LEFT
MIEU3065694	BENT	FRONT

Without any liability accepted  
 Constantia South Container Terminal  
 Planning Department

MV "CAPE MALE"  
 CALL SIGN: V7RU3  
 OFF-No.: 3580  
 GRT: 35878  
 POWER: 25040 KW

SIGNED AS RECEIPT ONLY AND NOT ACCEPTANCE  
 OF RESPONSIBILITY. CARGO DISCHARGED AS  
 LOADED.

Container	Damage type	Damage location
MSKU9768269	BENT	LEFT
HASU4812797	DENT	LEFT
TLLU5967896	DENT	RIGHT
MRKU7039585	BENT	LEFT
SEGU4099400	BENT	RIGHT
MRKU3028920	BENT	RIGHT
SUDU6622947	DENT	RIGHT
GAOU7159886	DENT	RIGHT
SUDU8747959	DENT	RIGHT
GCXU5574982	DENT	RIGHT
XINU1465106	BULGED	BOTTOM
TCNU8637095	BENT	RIGHT
MAEU4171159	CUT	TARPAULIN
MAEU4171159	BENT	RIGHT
MAEU4171159	BENT	LEFT
TCKU6154391	DENT	LEFT
MRKU6587898	BENT	LEFT
MRKU7512131	BENT	LEFT
MSKU1366392	BENT	LEFT
MRKU3566000	TORN	CORNER
MSKU0526618	DENT	LEFT
MMAU1268970	BENT	LEFT
MSKU1461830	BENT	RIGHT
SUDU5967266	DENT	RIGHT
MSKU1128753	DENT	RIGHT
MRKU4368083	BENT	RIGHT
MRKU4368083	DENT	RIGHT
MRKU2034071	BENT	RIGHT
MRKU2034071	DENT	LEFT
HASU4359269	DENT	LEFT
MSKU4105010	DENT	LEFT
MAEU4071057	CUT	TARPAULIN
MRSU4668993	DENT	LEFT
MSKU0670986	BENT	RIGHT

Without any liability accepted  
 Constantia South Container Terminal  
 Planning Department

MV "CAPE MALE"  
 CALL SIGN: V7RU3  
 OFF-No.: 3580  
 GRT: 35878  
 POWER: 25040 KW

SIGNED AS RECEIPT ONLY AND NOT ACCEPTANCE OF RESPONSIBILITY. CARGO EXCHANGED AS LOADED.



Container	Damage type	Damage location
TCLU3677159	BENT	FRONT
CAAU6451910	DENT	RIGHT
MRKU8560089	BENT	DOORSYSTEM
TCKU7420731	BENT	LEFT
MRKU2332965	DENT	RIGHT
MRKU2332965	DENT	LEFT
MSKU8548803	DENT	LEFT
MSKU8877141	DENT	LEFT
MSKU3259109	DENT	LEFT
MRKU4740734	DENT	RIGHT
PONU8036026	DENT	RIGHT
PONU8036026	DENT	LEFT
MRSU5213330	DENT	RIGHT
MRSU3594094	DENT	RIGHT
MSKU9854412	DENT	RIGHT
MSKU1996391	DENT	RIGHT
SUDU1840165	DENT	LEFT
MRKU4671295	DENT	LEFT
MRKU8872003	DENT	RIGHT
SUDU6998425	BENT	LEFT

Without any liability accepted  
 Constantia South Container Terminal  
 Planning Department

MV "CAPE MALE"  
 CALL SIGN: V7RU3  
 OFF-No.: 3580  
 GRT: 35878  
 POWER: 25040 KW

SIGNED AS RECEIPT ONLY AND NOT ACCEPTANCE OF RESPONSIBILITY.  
 CARGO UNCHANGED AS WOULD.